

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Hiller UH12L(4) Helicopter '65-66

Engine: TIVO540A2A

System comprises:

Turbocharger
404830-9001
(73895)

Wastegate
470656-9000
(73897)

Controller
470654-9000
(73898)