

PLANE SUPPORT is the trading name for AEROTEST PTY LTD
ABN 12 079 212 981 ian@planesupport.com P. 61 7 5448 9824 F. 61 7 5448 9287
Sunshine Coast Airport Mudjimba Qld 4564 Australia

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA46-310P Malibu

Engine: TSIO520BE

System comprises:

Turbocharger (LH & RH)
466304-9003
(646677)

Wastegate
481064-9002
(646317)

Controller
481058-9004
(646318-4)

P.R. Valve
470944-9009
(639319-9)

Aircraft: Piper PA46-350P Malibu

Engine: TIO540-AE2A

System comprises:

Turbocharger
466642-9005
(46C19839)

Wastegate
470954-9007
(47J21296)

Controller
481008-9032
(48E21297)

Aircraft: Piper PA60-602P Aerostar

Engine: IO540AA1A5

System comprises:

P.R. Valve
470944-9030
(LW-14445-11)

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA60-700P Aerostar Engine: TIO540U2A

System comprises:

P.R. Valve
470944-9007
(LW-14445-2)

Aircraft: Piper PA28 (R) (T)-201T Arrow, Dakota Engine: TSIO360F

System comprises:

P.R. Valve
481028-9001
(641404-1)

Aircraft: Piper PA23A,B-STC Aztec A,B '60-64 Engine: O540A1D5,B5

System comprises:

Turbocharger
406330-9001
(406330-1)

Wastegate
470656-9000
(470656-0)

Controller
470688-9003
(470688-3)

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA23C,D-STC Aztec C,D '66-69 **Engine:** IO540J4A5, C4B5

System comprises:

<u>Turbocharger</u>	<u>Wastegate</u>	<u>Controller</u>
406610-9003 (406610-3)	470656-9001 (470656-1)	470688-9004 (407688-4)

Aircraft: Piper PA(E)23-250 Aztec E,F '70-71 **Engine:** TIO540C1A

System comprises:

<u>Turbocharger</u>	<u>Wastegate</u>	<u>Controller</u>	<u>2nd Controller</u>
406610-9021 (LW-12950)	470818-9003 (LW-12778)	470884-9004 (LW-10682)	470886-9002 (LW-10098)
406610-9023 (LW13720)			

Aircraft: Piper PA31-350 B Eng T1020 '83-up **Engine:** (L) TIO540J2B

System comprises:

<u>Turbocharger</u>	<u>Wastegate</u>	<u>Controller</u>	<u>2nd Controller</u>
409170-9001 (LW-12463)	470818-9003 (LW-12778)	470886-9002 (LW-10098)	470884-9010 (LW-16840)

PLANE SUPPORT is the trading name for AEROTEST PTY LTD
ABN 12 079 212 981 ian@planesupport.com P. 61 7 5448 9824 F. 61 7 5448 9287
Sunshine Coast Airport Mudjimba Qld 4564 Australia

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA31-350 BD Eng Chieftain Engine: (L) TIO540J2BD

System comprises:

Turbocharger
409170-9001
(LW-12463)

Wastegate
470818-9003
(LW-12778)

Controller
470884-9010
(LW-16840)

2nd Controller
470886-9002
(LW-10098)

Aircraft: Piper PA32RT-300T Lance Engine: TIO540S1AD

System comprises:

Turbocharger
406610-9026
(LW-15749)

P.R. Valve
470944-9029
(LW-14445-10)

Aircraft: Piper Malibu

System comprises:

Wastegate
470954-9007

Controller
481008-9032

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA31P-350 Mojave

Engine: TIO540V2AD

System comprises:

Turbocharger
465680-9005
(LW-18470)

Wastegate
470954-9005
(LW-18861)

Controller
481008-9025
(LW-18518)

P.R. Valve
470944-9010
(LW-14445-4)

Aircraft: Piper PA31 Navajo (-310) '67-up

Engine: TIO540A All

System comprises:

Turbocharger
406610-9020
(LW-12689)

Wastegate
470818-9003
(LW-12778)

Controller
470912-9001
(LW-10644)

406610-9024
(LW-13721)

Aircraft: Piper PA31 Navajo (-310) '67-71

Engine: TIO540A1A, A2A

Controller
470654-9001
(75992)

PLANE SUPPORT is the trading name for AEROTEST PTY LTD
ABN 12 079 212 981 ian@planesupport.com P. 61 7 5448 9824 F. 61 7 5448 9287
Sunshine Coast Airport Mudjimba Qld 4564 Australia

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA31 Navajo (-310) '67-71 Engine: TIO540A1B, A2B

Controller
470884-9004
(LW-10682)

Aircraft: Piper PA31 Navajo (-310) '71-up Engine: TIO540A2C

Controller
470884-9004
(LW-10682)

Aircraft: Piper PA31-325 Navajo C/R '75-up Engine: (L) TIO540F2BD

System comprises:

Turbocharger
406610-9020
(LW-12689)

Wastegate
470818-9010
(LW-14283)

Controller
470912-9001
(LW-10644)

2nd Controller
470884-9004
(LW-10682)

Aircraft: Piper PA35 Engine: TIO720B

System comprises:

Turbocharger
406970-9003
(LW-10209)

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA40

Engine: GTSIO520P

System comprises:

P.R. Valve
481066-9002
(643511-2)

Aircraft: Piper PA41P

Engine: TIO540L

System comprises:

Turbocharger
407230-9002
(LW-12957)

Controller
481006-9001
(LW-12959)

P.R. Valve
470944-9008
(LW-12961)

Aircraft: Piper PA31P Pr. Navajo '70-77

Engine: TIGO541E

System comprises:

Turbocharger
407800-9003
(LW-13234)

Wastegate
470818-9005
(LW-10759)

Controller
481008-9010
(LW-14298)

P.R. Valve
470944-9011
(LW-14445-3)

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA32(R)-301T Saratoga

Engine: TIO540S1AD

System comprises:

Turbocharger
406610-9026
(LW-15749)

P.R. Valve
470944-9029
(LW-14445-10)

Aircraft: Piper PA44-180T Seminole

Engine: (L) TO360E1A6D

System comprises:

Turbocharger
465398-9002
(LW-16264)

P.R. Valve
481028-9003
(LW-16265-1)

Aircraft: Piper PA34-200T Seneca II

Engine: (L) TSIO360 E & EB

System comprises:

Turbocharger
466240-9001
(646606)

P.R. Valve
481028-9001
(641404-1)

PLANE SUPPORT is the trading name for AEROTEST PTY LTD
ABN 12 079 212 981 ian@planesupport.com P. 61 7 5448 9824 F. 61 7 5448 9287
Sunshine Coast Airport Mudjimba Qld 4564 Australia

TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: Piper PA34-220T Seneca III

Engine: (L) TSIO360KB

System comprises:

Turbocharger
466240-9001
(646606)

P.R. Valve
481066-9001
(643511-1)

Aircraft: Piper Various

Engine: TIGO480

System comprises:

Turbocharger
465680-9002
(LW-14206-Y)

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.