

PLANE SUPPORT is the trading name for AEROTEST PTY LTD

ABN 12 079 212 981 ian@planesupport.com P. 61 7 5448 9824 F. 61 7 5448 9287

Sunshine Coast Airport Mudjimba Qld 4564 Australia

RAJAY TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: CESSNA **Engine:** Teledyne Continental Motors (TCM)
*** Please check engine model - aircraft could be fitted with any of the following

**** Note: Part Numbers below are applicable to all the aircraft models listed.

<u>Aircraft Model</u>	<u>Engine Model</u>	<u>O.E.M. Part No.</u>	<u>Turbo Model</u>	<u>Turbo Part No.</u>
180	O-470-A	RJ0080-100	3DT5FF10J2	600572-00
180A	O-470-J			
180B	O-470-K			
180C	O-470-L			
180D	O-470-R			
180E				
180F				
180G				
180H				
180J				

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

Aerocomponents Pty Ltd

23 Benronalds Street, Seventeen Mile Rocks Qld 4073

Ph: 61 7 3376 8022 Fax: 61 7 3376 7800 Email: aerocomponents@ozemail.com.au

RAJAY TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: CESSNA **Engine:** Teledyne Continental Motors (TCM)
*** Please check engine model - aircraft could be fitted with any of the following

**** Note: Part Numbers below are applicable to all the aircraft models listed.

<u>Aircraft Model</u>	<u>Engine Model</u>	<u>O.E.M. Part No.</u>	<u>Turbo Model</u>	<u>Turbo Part No.</u>
182	O-470-L	RJ0080-100 or RJ0080-102	3DT5FF10J2	600572-00
182A	O-470-R			
182B				
182C				
182D				
182E				
182F				
182G				
182H				
182J				
182K				
182L				
182M				
182N				
182P				

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

Aerocomponents Pty Ltd

23 Benronalds Street, Seventeen Mile Rocks Qld 4073

Ph: 61 7 3376 8022 Fax: 61 7 3376 7800 Email: aerocomponents@ozemail.com.au

RAJAY TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: CESSNA **Engine:** Teledyne Continental Motors (TCM)
*** Please check engine model - aircraft could be fitted with any of the following

**** Note: Part Numbers below are applicable to all the aircraft models listed.

<u>Aircraft Model</u>	<u>Engine Model</u>	<u>O.E.M. Part No.</u>	<u>Turbo Model</u>	<u>Turbo Part No.</u>
210	IO-470-E	RJ0080-100	3DT5FF10J2	600572-00
210A	IO-470-S			
210B				
210C				
210-5 (205)				
210-5A (205A)				

Aircraft: CESSNA **Engine:** IO-470-O Teledyne Continental Motors (TCM)

**** Note: Part Numbers below are applicable to all the aircraft models listed.

<u>Aircraft Model</u>	<u>Engine Model</u>	<u>O.E.M. Part No.</u>	<u>Turbo Model</u>	<u>Turbo Part No.</u>
310C	IO-470-O	RJ0080-102	3DT5FF10J2	600572-00
310D				
310E				
310F				
310G				

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.

Aerocomponents Pty Ltd

23 Benronalds Street, Seventeen Mile Rocks Qld 4073

Ph: 61 7 3376 8022 Fax: 61 7 3376 7800 Email: aerocomponents@ozemail.com.au

RAJAY TURBOCHARGER SYSTEMS

- * These are generally stock items but please call for component availability.
- * Same day turn around to overhaul your units.
- * Exchange cores to be returned within 30 days or a core charge will apply. Refer to our Component Exchange Policy.

Aircraft: CESSNA Engine: IO-470-U Teledyne Continental Motors (TCM)

**** Note: Part Numbers below are applicable to all the aircraft models listed.

<u>Aircraft Model</u>	<u>Engine Model</u>	<u>O.E.M. Part No.</u>	<u>Turbo Model</u>	<u>Turbo Part No.</u>
310I 310J	IO-470-U	RJ0080-102	3DT5FF10J2	600572-00

Please note: While all care has been taken to ensure the data contained herein is accurate, you should ultimately rely on the data contained in the manufacturers Maintenance Manual and all other relevant manuals and advisories.